

# BOBBER TFC INSTRUMENT CALIBRATION DOWNLOADS



## Notice Information

Ref	14409
Posted Date:	
Posted To:	General Manager / Business Owner, Technician, Service Leader / Advisor
Subject:	Service/Technical

**TOL NOTICE (US&CA) – April 3, 2020**  
**SVC**

**TOL Ref. # 14409-**

## BOBBER TFC INSTRUMENT CALIBRATION DOWNLOADS

It has come to our attention that the instrument calibrations for Bobber TFC currently available in the Triumph Diagnostic Tool (TDT) are incorrect and, if downloaded to a bike during PDI, will not allow the engine ECM to be unlocked.

Therefore you must not carry out any instrument calibration downloads on this model until further notice.

To confirm: Bobber TFC models are all being delivered to you with the latest calibration (TYPE6-MPH-P22 or TYPE6-KMH-P22) already installed and it is not necessary to update the instruments to unlock the bikes at PDI.

If attempting an instrument calibration download to Bobber TFC models using Automatic Model Detection, the TDT will notify you that no update is required.

As a reminder, Bobber TFC motorcycles are scheduled to arrive to North American dealerships in late April.

If you have any questions, please contact Triumph Customer Support at (888) 284-6288.