

GPOP - Issue Review System

Part Number: 68275945A\$, 68275944A\$

Part Description: HEADLAMP

Issue Description: After performing the headlamp condensation clearing service procedure in Service Library (#0820118820), If the headlamp(s) is/are being replaced for a Moisture/Condensation issue, please e-mail pictures of the Moisture/Condensation issue to:
FCA Redacted Content

Then proceed with the repair.

Questions?: Call FCA Redacted Content.

~ _____ ~
Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
