

## GPOP - Issue Review System

**Part Number:** 68316081A\$, 68316080A\$, 68316087A\$, 68316086A\$

**Part Description:** Headlamp

**Issue Description:** After performing the headlamp condensation clearing service procedure, If the headlamp is being replaced for a Moisture/Condensation issue, please e-mail pictures of the Moisture/Condensation issue as part of the repair to:  
FCA Redacted Content

~  
Contact us at [CAGRIS@Chrysler.com](mailto:CAGRIS@Chrysler.com) for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.

