

Warranty information: Extended Warranty for Wheel Speed Sensors (122/19)

Model Line: **Macan (95B)**

Model Year: **As of 2014 up to 2018**

Country/Market: USA
Canada
Puerto Rico

Subject: **Wheel speed sensors, front and rear** – PART ID 4511 and 4515

Situation: **Extended warranty for front and rear wheel speed sensors**

The warranty on the wheel speed sensors lasts for **ten years as from the new vehicle delivery date** with unlimited mileage.
You will find the exact warranty period of a vehicle in the vehicle information in the PCSS – Porsche Central Service System.

The extended warranty is displayed as an additional new vehicle warranty scope and contains the added information "**Extended Warranty Speed Sensor**" in the "Coverage" column.

The warranty applies **only in the USA, Canada, Puerto Rico** and is always transferred automatically to the next owner.

All other terms and conditions specified in the Warranty and Maintenance booklet remain unchanged.

Overview of components covered by the warranty extension

PART ID	Designation
4511	Front speed sensor
4515	Rear speed sensor

Information: **Scopes not covered by this extended warranty**

Any damage or malfunctions caused by external influences such as damage as a result of an accident, incorrect use or neglect of the vehicle.

Restrictions on cover of the extended warranty

The warranty and service information in the vehicle includes information about the warranty conditions for the vehicle. The owner should always read these warranty conditions carefully as the rights and obligations listed there also apply for the extended warranty.

Invoicing: For processing warranty claims using the "Extended Warranty Speed Sensor", the claim must be entered by specifying **Warranty type 111** under **PART ID 4511 – Front wheel speed sensor** or under **PART**

ID 4515 – Rear wheel speed sensor (depending on where the problem occurred) as the **component responsible for causing the problem**.

If you have further questions and concerns relating to this extended warranty, get in touch with the contact person responsible for warranty enquiries at your importer's office.

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.

© 2020 Porsche Cars North America, Inc.