

2. Disassemble carburetor as follows:
 - a. Remove throttle cable bracket. Remove carburetor top from body.
 - b. Remove vacuum piston chamber components. Destroy and discard the old jet needle.
3. Assemble carburetor as follows:
 - a. Install vacuum piston chamber components using **new** jet needle from kit. The **new** needle has the letters "NCQB" stamped on it.
 - b. Install carburetor top to body. Install throttle cable bracket.




Figure 1. Install Silver "0603" Label on Carburetor (Optional)

4. **New** kits do not have the silver "0603" label, this is by design. Verify if labels are present in your kit.
 - a. **Yes:** Labels are present: Go to Step 5.
 - b. **No:** Labels are **not** present: Go to Step 6.

NOTE

Before application of label, thoroughly clean affected area with isopropyl alcohol and wipe dry with a clean cloth.

5. As proof of recall service, remove plastic backing to expose adhesive and firmly press silver "0603" label from kit onto rib of carburetor housing. Place label immediately above or below existing label bearing carburetor part number. While some overlapping of the labels may be unavoidable, please make an effort to keep overlap at a minimum. See Figure 1.
6. Install carburetor. See Section 4.4 CARBURETOR, INSTALLATION.

Credit Procedure

Jet Needle Kit (Part No. 94114)

Complete a Dealer Service Card for each motorcycle serviced. Write recall code "0603" on the card and place the letter "C" in the letter box. When the properly completed Dealer Service Card is received by Harley-Davidson, you will be credited 0.6 hour of labor for performing the recall procedure, which includes 0.1 hour for dealer administration time. No credit will be issued for parts as they were sent no charge.

For those motorcycles that do not have the original carburetor installed, please place the letter "U" in the letter box for "unable or ineligible" to have the recall service performed. In these instances, you will be credited 0.1 hour for dealer administration time only.

NOTE

Submitting the properly completed Dealer Service Card for each circumstance will enable Harley-Davidson to accurately report service activity on this recall, as is required.