



Bulletin No.: PIC6403B

Published date: N/A

# Preliminary Information

## PIC6403B Diagnostic Tip – Programming Modules on General Motors Next Generation Digital Electrical Architecture (VIP)

### Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Cadillac	CT4	2020	ALL	ALL	ALL	ALL
Cadillac	CT5	2020	ALL	ALL	ALL	ALL
Chevrolet	Corvette	2020	ALL	ALL	ALL	ALL

Involved Region or Country	North America
Condition	Programming modules on Next Gen Digital Architecture
Cause	New technology

### **Correction:**

When it is required to SPS program a module on a 2020 Cadillac CT4, CT5, or Chevrolet Corvette the power mode needs to be OFF with the vehicle fully asleep.

Ensure that the vehicle is not woken up during the programming event by opening a door or using a transmitter. Follow all SPS on screen instructions.

Use of a MDI2 is required for all programming and diagnostics.

Currently Techline Connect is not configured to program modules on 2020 Cadillac CT4, CT5, or Chevrolet Corvette, Use Stand Alone TIS2Web.

### Additional SI Keywords

VIP

### Version History

Version	2
Modified	02/05/2020 - Created on 05/19/2020 - Added Cadillac CT4 and Chevrolet Corvette. 05/19/2020 - Added Additional SI Keywords



GENERAL MOTORS