



Preliminary Information

PIT5686A Adding or Installing a Rearview Camera

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado 4500HD, 5500HD, 6500HD	2019 - 2020	All	All	All	All

Supersession Statement

This PI was superseded to update Model Years. Please discard PIT5686.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Involved Region or Country	North America
Additional Options (RPO)	UVC
Condition	A Dealer or Upfitter may be looking for information on installing the factory provided rearview camera (RPO UVC.) Note: Camera, Extension Harness, and Mounting Bracket are shipped with the vehicle from the assembly plant.
Cause	Information not readily available in Service Information (SI.)

Correction:

Reference the latest version of GM Upfitter Integration Bulletin 150. The information can be found at <http://www.gmupfitter.com/> under the "Technical Bulletin" Tab and then "Show all bulletins."

Version History

Version	2
Modified	05/17/2019 - Created on. 05/26/2020 - Update to add 2020 Model Year

