

GPOP - Issue Review System

Part Number: 68323529A\$, 77072424A\$

Part Description: Two-inch Lift Kit (Rear Shock)

Issue Description: When installing the Mopar 2 Inch Lift Kit do not compress the rear shocks fully, as the rear shocks can be over-compressed prior to being installed; leading to damage of the shaft seal.
Please go to STAR parts and download the latest I-sheet K6862538AC for further details. Lift Kit 77072424AC or later will have the updated I-sheet.
NOTE- shocks with this type of damage are not considered warranty.

~ _____ ~
Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
