



Service Information System

Previous Screen

Welcome: lanets

< Product: NO EQUIPMENT SELECTED
Model: NO EQUIPMENT SELECTED
Configuration: NO EQUIPMENT SELECTED

Engine News

New Engine Software is Now Used for Certain 3126E through C18 Engines {1920}

Media Number -M0116649-00

Publication Date -2020/06/15

Date Updated -2020/06/15

i08042878

New Engine Software is Now Used for Certain 3126E through C18 Engines {1920}

SMCS - 1920

Engine

C-12 (S/N: 9SM1-13216)

C-18 (S/N: MEP1-2566)

C7 (S/N: RMF1-14291; FML1-38109; FMM1-55402; JRT1-3222)

C9 (S/N: LFE1-4688)

Description Of Change: The new engine software used helps prevent an engine will not issue caused by the Battery-Backed RAM (BBram) battery running out of life.

The new software implements one key cycle programming of the Electronically Erasable Programmable Read Only Memory (EEPROM) to the BBram per the 2007On-Highway **Truck** program.

Adaptable To:



Do not operate or work on this product unless you have read and understood the instruction and warnings in the relevant Operation and Maintenance Manuals and relevant service literature. Failure to follow the instructions or heed the warnings could result in injury or death. Proper care is your responsibility.

The following changes are adaptable to the products within the listed serial numbers, and are effective with all products after the listed serial numbers.

Table 1 contains the new software part numbers for this change.

Table 1

Required Software		
New Part Number	Part Name	Former Software Part Numbers ⁽¹⁾

595-0656	Engine Software	362-0656
596-3667	Engine Software	557-4444
596-3671	Engine Software	557-4455
596-3667	Engine Software	559-4444
596-3671	Engine Software	557-4455
599-4819	Engine Software	353-8652
599-4820	Engine Software	353-8654
599-4824	Engine Software	353-8653
599-4826	Engine Software	353-8655

(1) The former part number listed is for reference only and may differ.

The new software is available in the form of a flash file through the Caterpillar Service Information System (SIS). A newer part number may be available. SIS Web only displays the latest available flash file.