

Latest Vehicle Concern Fixes

BODY



Windshield Sealing

20MY Discovery

Customer Voice:

- A customer may report that there is a water leak from the windshield area.

Technical Description:

- There are a couple different potential sealing concerns relating to the windshield.
 - PU adhesive not sealing correctly to windshield glass
 - PU adhesive not sealing correctly to the vehicle body
 - Air gaps in the PU adhesive

Status:

- Engineering requests your support in identifying the root cause of the sealing concern.
- Please submit an EPQR with pictures showing what exact issue has caused the windshield to leak.
- Please include a picture of the windshield information in the lower left corner near the VIN cutout. It works best to place a piece of paper behind the windshield data to make it stand out better in pictures.

