

## CAMPAIGN LAUNCH STATUS

### N458 - SERVICE ACTION - L551 PARTICULATE MASS EMISSIONS



SERVICE ACTION N458 - PARTICULATE MASS EMISSIONS	
AFFECTED MODELS	20MY RANGE ROVER EVOQUE
VEHICLES AFFECTED	3976 USA, 596 CAN
REPAIR	Affected vehicles require revised PCM and TCM calibrations
REPAIR TIME	0.2 hrs+ drive in/out
CAMPAIGN LAUNCH	06/15/2020

- Certain 20MY Range Rover Evoque vehicles require a software update to the powertrain control module (PCM) and transmissions control module (TCM) to ensure the certified emissions standards are achieved.
- Approx. 80 affected cars are in retailer inventory and require this update prior to sale. These will be identified in BBSS
- This service action is subject to a Californian Air Resource Board (CARB) approval as an emission recall. Once CARB approval is granted the campaign will be classified as an emission recall and customers will be notified by mail.