

NEW DIAGNOSTIC SOFTWARE 6.1 RELEASE



Notice Information

Ref	14947
Posted Date:	
Posted To:	General Manager / Business Owner, Technician, Aftersales Manager, Service Leader / Advisor, Accounts / Admin
Subject:	Service/Technical

TOL NOTICE (US&CA) – June 8, 2020, 2020
Ref. # 14947-SVC

TOL

NEW DIAGNOSTIC SOFTWARE 6.1 RELEASE

Triumph has released version 2020-6.1 of the diagnostic software. Below is a summary of the changes in this latest version.

1. NEW SOFTWARE FUNCTIONALITY

None

2. ENGINE ECM CALIBRATIONS

- New calibrations released for Scrambler 1200 Bond edition.
- Updated calibrations released for Tiger 900, Tiger 900 GT, Tiger 900 GT-LRH, Tiger 900 GT Pro, Tiger 900 Rally and Tiger 900 Rally Pro.

3. CHASSIS ECM CALIBRATIONS

None

4. INSTRUMENT CALIBRATIONS

- New calibrations released for Scrambler 1200 Bond edition.

5. KEYLESS ECM CALIBRATIONS

- New calibrations released for Scrambler 1200 Bond edition.

6. CONNECTIVITY MODULE CALIBRATIONS

None

7. SUSPENSION ECM CALIBRATIONS

None

8. NEW ECU UNLOCK CODES

- None – Scrambler 1200 Bond Edition uses the same engine ECM unlock code as Scrambler 1200 XE.

9. CALIBRATION DESCRIPTION CORRECTIONS

None

10. Known Issues in This Release

None

11. Bug Fixes

None

If you have any questions, please contact Triumph Customer Support at (888) 284-6288.