



RYKER 2019-20 Noisy Fuel Pump - 136739

[Printable Version](#)

Rate This Article

(Average Rating: 3)

[Version 3](#)

Language

English ▼

[Show Properties](#)**Summary:**

Ryker's fuel pump noisy when low fuel level and warm temperatures.

Type:

General

TST Detail:**Problem:**

Reports that the fuel pump can be noisy especially when low fuel levels and warm temperatures.

Solution:

New proto part available, contact a BRP service representative for details.

[Ryker Fuel Pump Noise Modification - 137790](#)

Inspection Procedure:

Replace the fuel pump only if there are symptoms like check engine light leading to a fuel pump replacement or due to low fuel pressure only.

NOTE; Keeping the fuel level high will help to reduce the humming noise.

Warranty:

NA

Attachment:

Ryker fuel pump noise



First Published By: Eric Fauteux on 2019-08-06

Last Modified By: Eric Fauteux on 2020-07-17