

Subject		Market
<b>Body Lashing Plug Installation</b>		<b>USA</b>
Service Category	Section	
Vehicle Exterior	Body Structure	
Applicability		
Applicable Models		

APPLICABLE VEHICLES			
2020-2021	UX250H	2020-2021	IS350
2020-2021	LS500	2020-2021	RX450H
2020-2021	UX200	2020-2021	LC500
2020	GS F	2020-2021	IS300
2020	GS350	2020-2021	RX350
2020-2021	LS500H	2020-2021	RC300
2021	LC500C	2020-2021	RC350
2020-2021	LC500H	2020-2021	RC F

- CONDITION**
- Unibody vehicles commonly have lashing holes on the under body used for securing the vehicle during logistics.
  - The lashing holes are intended to be plugged during Pre-Delivery Service (PDS).
  - The plugs are
    - Required for anti-corrosion purposes.
    - Usually located in the glove box prior to PDS.
  - The number of plugs may be different based on model and production location.

**RECOMMENDATIONS**

- Reference the figure below to identify the location of the lashing holes.
- Closely follow the PDS Check Sheet for each model to ensure the plugs are installed.

*1	Torque box hole or Rocker inner hole	*2	Rr side member hole or Rocker inner hole
----	--------------------------------------	----	--

**LINK REFERENCES**

This Tech Tip does not contain any link references



Subject	Market
<b>Body Lashing Plug Installation</b>	USA
Applicability	
Applicable Models	