

Special Service Message

NOTE: A Special Service Message is a formal communication issued by Land Rover and carries the same importance of a Technical Service Bulletin. An SSM is a quick method of communicating "Need To Know" information to the technical service community. SSM's may be issued in advance of a technical bulletin or may be the only communication on a given topic. All information contained in Land Rover technical communications are intended for use by trained, professional technicians with the knowledge, tools, and equipment required to complete the procedure correctly and safely. It informs the Technicians of conditions that may occur on some vehicles, or provides information that could assist in correct vehicle and diagnostic service.

SSM 74895 - Engine Junction Box (EJB) - Corrosion - Lid Replacement

Models : Discovery Sport / L550

Evoque / L551

Engineer Shilvock Matthew

Name :

Last 15 JUL 2020 10:53:12

Modified :

Category : Electrical

Symptom : 205000 Electrical Accessories

Content :

Issue:

Corrosion in EJB (Engine Junction Box)

Cause:

Unknown

Action:

If an EJB (Engine Junction Box) needs to be replaced, Please ensure a lid is also ordered using the part number below.

K8D2-14A076-AD2/ LR146848