### LATEST VEHICLE CONCERN FIXES

#### ELECTRICAL





# **Battery Positive – Open Circuit**

### Customer Voice:

Customer finds they are unable to start the vehicle.


### Technical Description:


Potential water corrosion in junction box may cause a no start condition

### Status:

- This issue is still under investigation
- For no-start concerns please check cable at C4DC12 B, C, & D.
- If fault is found at that locations please repair and submit a EPQR
  - Provide which location the issue was found
  - Provide photos of the components
  - Hold parts for potential PRR

## 18 - Current MYRR Velar L560 17 - Current MY F-PACE X761













PRINTED COPIES ARE UNCONTROLLED