



Service Bulletin

Bulletin No.: 20-NA-110

Date: June, 2020

INFORMATION

Subject: Information on Diesel Exhaust Fluid Pump is Unable to Build Pressure After Replacement

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Colorado	2017	2020	-	-	LWN	-
	Cruze	2017	2020			LH7	
	Express	2017	2020			LWN	
	Equinox	2018	2019			LH7	
	Silverado	2017	2018			L5P	
	Silverado 1500 (New Model-12th VIN=7)	2019	2019			LM2	
	Silverado 1500	2020	2020			LM2	
	Silverado 2500/3500	2019	2020			L5P	
	Silverado 4500HD/5500HD/6500HD	2019	2020			L5D	
	Silverado LD	2019	2019			LM2	
GMC	Canyon	2017	2020	-	-	LWN	-
	Savanna	2017	2019			LWN	
	Sierra	2017	2018			L5P	
	Sierra 1500	2020	2020			LM2	
	Sierra 2500/3500	2019	2020			L5P	
	Sierra Limited	2019	2019			LM2	
	Terrain	2018	2019			LH7	

Involved Region or Country	North America
Condition	Some technicians may comment that after replacing the DEF pump, the pump won't build pressure and one or more of the following DTCs may set: <ul style="list-style-type: none"> • P20E8: Reductant Low Pressure • P249C: Excessive Time To Enter Closed Loop Reductant Injection Control
Information	If it has been determined that after replacing the DEF pump and confirmed proper operating that the system is unable to build pressure. Inspect for any leaks, loose connections or kinks in the supply line. After performing an initial leak test three times. If low pressure is present, this may be because the DEF pump filter has dried out. Allow the vehicle to sit overnight with the new pump and DEF fluid, to re-saturate the DEF pump filter. In the morning, perform the leak test three additional times. The pump should now be able to build pressure.

Parts Information

No parts are required for this repair.

Warranty Information

Important: Only apply the additional labor time if the vehicle requires overnight soak time and re-test.

For vehicles repaired under the Emission coverage, use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
4087458*	Perform DEF Pump Pressure Test.	0.4 hr
*This is a unique Labor Operation for Bulletin use only.		

Version	1
Modified	Released June 11, 2020

