

Complaint: C/S LP LEAK AT REFER, HE CAN SMELL A STRONG GAS ODOR WHEN THE LP IS ON.

Cause: Lp regulator is leaking out of small hole on lower side of housing, constant when lp switch is on. Can feel the gas blowing out of hole.:

Correction: Unbolted regulator bracket, cut plastic cover ends so cover can be removed without disconnecting lines, sprayed regulator with leak detect, but gas is blowing out of hole so fast it will not bubble for pictures. Will need to replace lp regulator and test system. Pays 1.0 hr.