

# SS 1034782 New Cascadia Bluetooth Microphone Relocation

---

SS 1034782 New Cascadia Bluetooth Microphone Relocation

## Applicable Vehicles

New Cascadia

## Symptom

Bluetooth microphone reception poor.

## Issue

Field complaints of the Bluetooth microphone not in a reasonable proximity to the driver resulting in having to shout to be heard.

## Solution

Relocation of the Bluetooth microphone directly over the driver has had some reported success in the field. See the attached document.

# New Cascadia Bluetooth Microphone Relocation

See the following slides for a simple relocation/retrofit

# New Cascadia Bluetooth Microphone Relocation



# New Cascadia Bluetooth Microphone Relocation

