



GROUP
ELE

MODEL
2018-2019
Niro (PHEV, EV)

NUMBER
202

DATE
August 2020

TECHNICAL SERVICE BULLETIN

SUBJECT: **SERVICE ACTION: IN-CABLE CONTROL BOX
PROTECTION COVER INSTALLATION (SA425)**

This bulletin provides information on the installation of the In-Cable Control Box (ICCB) / Level 1 Charge Cord protection cover on some Niro (PHEV/EV) vehicles listed below, in order to protect the ICCB from impact which can easily cause damage. Before conducting the procedure, verify the vehicle is included in the list of affected VINs.

MY	Model	Production Date Range
2018-2019	Niro (DE PHEV)	September 26, 2017 to June 19, 2019
2019	Niro (DE EV)	December 5, 2018 to June 19, 2019



★ NOTICE

A Service Action is a repair program without customer notification that is performed during the warranty period. Any dealer requesting to perform this repair outside the warranty period will require DPSM approval.

Repair status for a VIN is provided on WebDCS (Service → Warranty Coverage → Warranty Coverage Inquiry → Campaign Information). Not completed Recall / Service Action reports are available on WebDCS (Consumer Affairs → Not Completed Recall → Recall VIN → Select Report), which includes a list of affected vehicles.

This issue number is SA425.

Printed TSB copy is for reference only; information may be updated at any time.
Always refer to KGIS for the latest information.

Circulate To: General Manager Service Manager Parts Manager
 Service Advisors Technicians Body Shop Manager Fleet Repair


Installation Procedure:

1. Pull the inner bottom side openings outward from the ICCB protection cover (A).



2. Insert the ICCB device (B) into the protection cover (A) as shown.

The service action is complete.



SUBJECT:

SERVICE ACTION: IN-CABLE CONTROL BOX
PROTECTION COVER INSTALLATION (SA425)

AFFECTED VEHICLE RANGE:

Model	Production Date Range
Niro (DE PHEV)	September 26, 2017 to June 19, 2019
Niro (DE EV)	December 5, 2018 to June 19, 2019

REQUIRED PART:

Part Name	Part Number	Figure	Qty.
ICCB Protection Cover	91887 G7500QQK		1

WARRANTY INFORMATION:

N Code: N99 C Code: C99

Claim Type	Causal P/N	Qty.	Repair Description	Labor Op Code	Op Time	Replacement P/N	Qty.
V	91887 G5520	0	(SA425) ICCB Protection Cover Installation	200031R0	0.2 M/H	91887 G7500QQK	1

*** NOTICE**

VIN inquiry data for this repair is provided for tracking purposes only. Kia retailers should reference SA425 when accessing the WebDCS system.

