

Mack Chassis - Mileage Does Not Store At Key OFF



Reliability has been made aware that some EPA2010 MRU and LEU models may experience the odometer not storing mileage at key off. On a few cases that have been observed, the EPROM may contain a bad sector not allowing the next value to be stored.

Reprogramming the Gauge Driver Module (GDM, MID 140) DOES NOT fix this problem.

A replacement GDM, p/n 22392656, can be ordered, installed and programmed to fix the issue on vehicles which demonstrate this concern. This part is available in the PDC.

Click [here](#) for the original document.



Tags

[MILEAGE](#)

[KEY OFF](#)

Related links and attachments

[Mileage does not store at Key OFF](#)



Feedback

[Give feedback](#) to help improve the content of this article