

Subject: Engineering Information – Oil Leaking From Oil Pan

This PI has been revised to end the need for information from the field. Please discard PIE0563A.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Silverado 1500	2020	2020	-	-	Equipped with 2.7L Engine (RPO L3B)	-
GMC	Sierra 1500						

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

Version	3
Modified	Released April 02, 2020 Revised May 07, 2020 – Remove 2019 Model Year. Revised July 08, 2020 – Ended the need for further information from the field.