

ROCKET 3 SERVICE TOOLS SHIPPING



Notice Information

Ref	15501
Posted Date:	
Posted To:	General Manager / Business Owner, Technician, Service Leader / Advisor, Accounts / Admin
Subject:	Service/Technical

TOL NOTICE (US&CA) – August 4, 2020**TOL Ref. # 15501-SVC****ROCKET 3 SERVICE TOOLS SHIPPING**

To further equip you to effectively service new Rocket 3 motorcycles, six (6) new service tools will be required. Please be on the look-out for the new tools described below which have been auto-shipped to your dealership.

Part Number	Description	Models Affected
T3880502	Cam shaft timing bar	Rocket 3 R , Rocket 3 GT & Rocket 3 TFC
Reason for introduction		Release of service tool for engine
Part Number	Description	Models Affected
T3880505	Main frame support	Rocket 3 R , Rocket 3 GT & Rocket 3 TFC
Reason for introduction		Release of service tool for new Rocket
Part Number	Description	Models Affected
T3880511	Needle bearing installer 6.5MM	Rocket 3 R , Rocket 3 GT & Rocket 3 TFC
Reason for introduction		Release of service tool for chassis
Part Number	Description	Models Affected
T3880512	Needle bearing installer 7.5MM	Rocket 3 R , Rocket 3 GT & Rocket 3 TFC

Reason for introduction		Release of service tool for chassis
Part Number	Description	Models Affected
T3880513	Adaptor 12MM	Rocket 3 R , Rocket 3 GT & Rocket 3 TFC
Reason for introduction		Release of service tool for chassis
Part Number	Description	Models Affected
T3880514	Kit oil spray jet protectors	Rocket 3 R , Rocket 3 GT & Rocket 3 TFC
Reason for introduction		Release of Release of service tool kit

If you have any additional questions, please contact Triumph Customer Support at (888) 284-6288.