

# MIL "ON" DTC P0A80 or P0A7F Due to Dust or Debris in the HV Battery Cooling Fan

**Service Category** Engine/Hybrid System

**Section** Hybrid/Battery Control System

**Market** USA

Toyota Supports  
ASE Certification 

## Applicability

YEAR(S)	MODEL(S)	ADDITIONAL INFORMATION
2013 - 2014	Camry HV	

### **OBSOLETE NOTICE**

**August 13, 2020: This bulletin is no longer applicable and is now obsolete.**