

2020 P4 Speedometer issues



[Rob Layne](#) 27 posts since Dec 4, 2014

2020 P4 Speedometer issues Feb 5, 2020 1:41 PM

Just want to spread the word incase anyone runs into this... There's been a bunch of new trucks on the east coast, new P4's with Eaton 10 speed transmissions with erratic speedometer operation.. Turns out the factory has been installing the wrong speed sensor.

It is supposed to be a brown speed sensor, P/N 66-04114-002. Instead they're seeing a black speed sensor being installed, P/N 66-04114-001. Parts Pro calls for the brown one, but that is not what is being installed, and from what I've read, the brown one's are not readily available.

So, just a heads up....

Tags: speed sensor



[Scott Trippel](#) 3,902 posts since Dec 13, 2014

Re: 2020 P4 Speedometer issues Feb 5, 2020 3:37 PM

Thanks for the tip Rob



[Robert Cadell Jr](#) 2,593 posts since Nov 9, 2014

Re: 2020 P4 Speedometer issues Feb 5, 2020 3:39 PM

Thanks Rob



[Talbert Simonian](#) 1,742 posts since Nov 21, 2014

Re: 2020 P4 Speedometer issues Feb 5, 2020 6:04 PM

Thanks for the heads up [Rob Layne](#). I am going to use this in our shop meeting today. Thanks for reminding me.



[Don Kautzman](#) 72 posts since Jun 9, 2016

Re: 2020 P4 Speedometer issues Feb 6, 2020 2:34 PM

Thanks Rob

This will save a lot of troubleshooting time and lost revenue .



[Mike Sparkes](#) 233 posts since Jan 14, 2015

Re: 2020 P4 Speedometer issues Aug 8, 2020 5:29 PM

Ran into this issue today (from a parts perspective)

KX9775 calls out 66-04114-001 in parts list 817 - verified part number off the failed sensor, yes it was -001

2020 P4 Speedometer issues

No stock available & Paragon subs it to -002

We have 4 66-04114-002 on order but not released as part is under investigation...???

So we took a -002 from a new stock unit & installed - tech said the unit then threw a bunch of codes that were not there before. Found another stock unit that had -001, installed and all problems were solved.

Has anyone else had this issue or can provide some insight?



[Mike Sparkes](#) 233 posts since Jan 14, 2015

Re: 2020 P4 Speedometer issues Sep 17, 2020 11:49 AM

Answer finally came....

66-04114-001 is for CPC3 Evo (KX9775 w/ RTLO-18913A)

66-04114-002 is for CPC5 (MM1062 w/ RTLO-18913A)

Parts supersession is gone from Paragon



[Kyle Siebert](#) 3,913 posts since Nov 14, 2014

Re: 2020 P4 Speedometer issues Sep 17, 2020 4:36 PM

Great info Mike. Thanks for sharing.