

BLUE TOOTH VOLUME DROPS OUT IN W/STAR



[Grant Overton](#) 111 posts since Nov 14, 2014

BLUE TOOTH VOLUME DROPS OUT IN W/STAR Mar 30, 2020 7:20 PM

LP2460 BLUETOOTH DROPS VOLUME CONTROL, AS THIS IS A WESTERN STAR THE DRIVER HAS TO KEEP PLAYING AND RESTARTING HIS PHONE TO SYNC AND RECONNECT THE BLUE TOOTH,

RADIO A22-74935-000 = PSO PP15160 IN THE 2019 DEALER SERVICE MANAGERS WORKSHOP THE SOLUTION WAS TO REPLACED RADIO WITH PP105715 IS THIS STILL THE OPTION OF CHOICE, OR DOES THE PLUG AND PLAY WITH UPDATING THE SOFTWARE WITH HARD BOOT - WORK ON THESE AS WELL AND WHERE DO WE GET THE DOWN LOAD FORM IF THIS IS THE CASE.



[Michael Palumbo](#) 1,372 posts since Nov 13, 2014

Re: BLUE TOOTH VOLUME DROPS OUT IN W/STAR Mar 31, 2020 12:20 AM

The radio software update bulletin does not apply to WS 4900.

Attached is the radios manual, from PanaPacific, the supplier of that Delphi radio.

Bluetooth TS at the back of the attachment does not look to be helpful.

On page 13 I read something about third party players that might apply. A good question for the customer at least.

Bluetooth Player

If your connected device supports this feature, it can be used as an audio source input to the radio, allowing you to enjoy the music files stored on your phone.

This feature is recommended to be used with the device default player. Functionality cannot be warranted, when a third party player is used in the connected device. The radio can be out of synchrony if the user alters or command the player within the phone.

You might also try: <http://www.panapacific.com/support>

- [DEA5XX_Owners_Manual_English_FULL1 \(3\).pdf](#) 1.2 MB Preview



[Grant Overton](#) 111 posts since Nov 14, 2014

Re: BLUE TOOTH VOLUME DROPS OUT IN W/STAR Sep 10, 2020 4:55 PM

BLUE TOOTH VOLUME DROPS OUT IN W/STAR

panapacific, HAS ADDED A NEW DOWNLOAD FOR THE 540 RADIOS, SEAMS TO BE WORKING, CONTACT pana pacific or myself I can EMAIL the DOWN LOAD if needed.

grant.overton@firsttruck.ca



Scott Trippel *3,902 posts since Dec 13, 2014*

Re: BLUE TOOTH VOLUME DROPS OUT IN W/STAR Sep 11, 2020 1:38 PM

I believe [Grant Overton](#) is correct I have added the letter in the attachment

- [Radio not respnding software update letter 54-074.pdf](#) 186.7 KB Preview