

## Mack Chassis - Stemco Hubcap Plug Will Not Stay In



On Mack models [GU](#), [GR](#) trucks built with hub cap [20421922](#) or using the [85105316](#) hub cap, the hub cap comes with a .787 inch (20 mm) diameter plug that has a vent slit. The Mack replacement part number for this plug is [23934917](#).

### Related links and attachments

No links or attachments available

These hub caps can also be retrofitted to utilize a larger diameter plug that has better venting capability. Kit number [85105366](#) contains a replacement sight glass and a larger diameter 1.312 inch (33.33 mm) plug [1577627](#). This larger plug has a hole to vent instead of a slit and is less susceptible to popping out.

**Note:** The 1.312 diameter is measured at the end of the flare. The diameter at the neck is smaller.



92103-5001

On Mack model [CXU](#), [CHU](#), [AN](#), [GR](#), [PI](#) trucks built with hub cap [25155452](#) or using the [7843-3434308](#) hub cap, the hub cap comes with a .787 inch (20 mm) diameter plug that has a vent slit. The Mack replacement part number for this plug is [23934917](#).

These hub caps can also be retrofit to utilize a larger diameter plug that has better venting capability. Kit number [85105366](#) contains a replacement sight glass and a larger diameter 1.312 inch (33.3 mm) plug [1577627](#). This larger plug has a hole to vent instead of a slit and is less susceptible to popping out.

**Note:** The 1.312 diameter is measured at the end of the flare. The diameter at the neck is smaller.



1577627

<b>Mack</b>		
	GR, GU	CXU,CHU,AN,GR,PI
Production Hub Cap P/N	20421922	25155452
Aftermarket Hub Cap P/N	85105316	7843-3434308
Hub Cap Plug, Small P/N	23934917	23934917
Hub Cap Plug, Large P/N	1577627	1577627
Hub Cap Retrofit Kit, which includes Large plug	85105366	85105366



Tags

[STEMCO](#)[HUBCAP](#)[PLUG](#)**Feedback**

[Give feedback](#) to help improve the content of this article