



## **WARRANTY ENHANCEMENT PROGRAM (WEP)**

**COE FUEL CUT VALVE – AAGP0**

**BULLETIN NO: WP-20-005**

**DATE: 9-3-2020**

**REF: QA-200831-N2**

**SUBJECT VEHICLES:** Certain 14MY-16MY Cab-Over Engine (COE) Trucks equipped with a J05 engine.

## **OVERVIEW:**

In certain conditions, the fuel pressure applied to the FCV (Fuel Cut Valve) during operation exceeds the valve opening force limit, this is because the design of the FCV may not have enough allowance for the pressure and timing of the fuel generated in the valve, causing the valve not to be opened temporarily.

**If this condition is found, refer to the appropriate Vehicle Identification Number in the warranty system to determine vehicle eligibility.**

## **Warranty Terms**

-Warranty enhancement program: 10 years with no mileage limitation from the delivery date to the initial end purchaser, or one (1) year from the date of the customer notification letter, whichever is longer, will be covered by this program.

For any other failure modes, standard warranty conditions will be applied.



## PARTS:

Part Number	Part Description	Quantity
S2210E0035	Fuel Cut Valve	1
SZ43010011	Soft Washer	2

## ***BEFORE YOU BEGIN:***

- Read and understand all instructions and procedures before you begin the work.
- Read and follow all **WARNINGS** and **NOTICES** set forth in this publication. These alerts help to avoid damage to components, serious personal injury, or both.
- Park the vehicle on a flat, level and solid surface.
- Place the gear shift lever in "Neutral" or "Park".
- Apply the parking brake firmly and confirm parking brake activation.
- Turn off the engine and remove the key from the ignition switch.
- Always wear safety glasses or goggles to protect your eyes.
- Place wheel chocks in front of and behind all the wheels to prevent the vehicle from moving.

## ***REPAIR PROCEDURE:***

Please refer to the Hino Service Manual for replacement instruction.

(Exhaust J05E)



## **CLAIM APPLICATION**

*Reimbursable in accordance within the terms and policies of the Hino limited warranties.*

### **Fuel Cut Valve Replacement:**

- a) Campaign No: AAGP0
- b) Labor charge: 0.4 hours
- c) Warranty code: 11553
- d) Trouble code: 98
- e) Operation code: 11550AOT
- f) Original failed part: 9999999999

