

Document Information

Location: Electrical Systems - Body Control System

Topic: Body Controller hardware update

Condition: N/A

Diagnostic Trouble Codes: N/A

Measure

A new 433MHz BC has been introduced in all 12C's from VIN SBM11AAB3DW002519, Production number 6753. Vehicles after this VIN should only be fitted with the most recent part number available.

When installing a new 433MHz BC to a vehicle that has the previous level part and, an external key signal filter (1) fitted, the filter must be removed as the new part incorporates the key signal filter onto the printed circuit board.

If a fault with the external key signal filter has been diagnosed and has to be replaced the only option is to replace the Body Controller with the latest part number.

Parts Information

N/A

Warranty Information

Resolution Category

Casual Part Number: N/A

Casual Part Name: N/A

Casual Issue: N/A

Rectification: N/A

Time: N/A

Attachments

N/A

KA Updates Information

N/A

This document is uncontrolled when printed. Before use, check the Knowledge Base within the McLaren Retailer Portal to verify that this is the current version.