

**Campaign:**

Dometic recall 20E071 recreational vehicle cooking stoves.

**Are you reporting a:**

Vehicle recall for Renegade RV LLC

**Descriptive Information To Include:**

Valencia VIN #s – 215 Total (192 in the field – 23 on grounds)

|                   |                   |                   |                   |                   |
|-------------------|-------------------|-------------------|-------------------|-------------------|
| 4UZADVFC0KCKL9343 | 4UZADVFC0MCMG7180 | 4UZADVFC2KCKL9361 | 4UZADVFC3KCKS0107 | 4UZADVFC4KCKS0116 |
| 4UZADVFC0KCKL9357 | 4UZADVFC0MCMG7194 | 4UZADVFC2KCKS0115 | 4UZADVFC3KCKS0110 | 4UZADVFC4KCKS0147 |
| 4UZADVFC0KCKL9360 | 4UZADVFC1KCKL9349 | 4UZADVFC2KCKS0146 | 4UZADVFC3KCKS0155 | 4UZADVFC4KCKS0150 |
| 4UZADVFC0KCKS0114 | 4UZADVFC1KCKS0154 | 4UZADVFC2KCKS0163 | 4UZADVFC3KCKS0169 | 4UZADVFC4KCKS0164 |
| 4UZADVFC0KCKS0145 | 4UZADVFC1KCKS0168 | 4UZADVFC2LCLW2854 | 4UZADVFC3KCLS7271 | 4UZADVFC4LCLW2855 |
| 4UZADVFC0KCKS0159 | 4UZADVFC1LCLW2859 | 4UZADVFC2LCLW2868 | 4UZADVFC3LCLW2846 | 4UZADVFC4LCLW2869 |
| 4UZADVFC0KCKS0162 | 4UZADVFC1LCLW2862 | 4UZADVFC2LCLW2871 | 4UZADVFC3LCLW2863 | 4UZADVFC4LCLW2872 |
| 4UZADVFC0LCLW2853 | 4UZADVFC1LCMA0778 | 4UZADVFC2LCMA0787 | 4UZADVFC3LCMA0779 | 4UZADVFC4LCMA0774 |
| 4UZADVFC0LCLW2867 | 4UZADVFC1LCMA0781 | 4UZADVFC2LCMA0790 | 4UZADVFC3LCMA0782 | 4UZADVFC4LCMA0788 |
| 4UZADVFC0LCLW2870 | 4UZADVFC1LCMA0795 | 4UZADVFC2LCMD3899 | 4UZADVFC3LCMC9148 | 4UZADVFC4LCMA0791 |
| 4UZADVFC0LCMA0786 | 4UZADVFC1LCMC9147 | 4UZADVFC2LCMD3904 | 4UZADVFC3LCMC9151 | 4UZADVFC4LCMD3905 |
| 4UZADVFC0LCMD3898 | 4UZADVFC1LCMC9150 | 4UZADVFC2LCME5048 | 4UZADVFC3LCMD3894 | 4UZADVFC4LCME5049 |
| 4UZADVFC0LCMD3903 | 4UZADVFC1LCMD3893 | 4UZADVFC2LCME5051 | 4UZADVFC3LCME5057 | 4UZADVFC4LCME5052 |
| 4UZADVFC0LCME5047 | 4UZADVFC1LCME5056 | 4UZADVFC2LCME5065 | 4UZADVFC3LCME5060 | 4UZADVFC4LCME5066 |
| 4UZADVFC0LCME5050 | 4UZADVFC1LCMG4299 | 4UZADVFC2LCMG4294 | 4UZADVFC3LCMG4305 | 4UZADVFC4LCMG4300 |
| 4UZADVFC0LCME5064 | 4UZADVFC1LCMG4304 | 4UZADVFC2LCMG4313 | 4UZADVFC3MCMG7173 | 4UZADVFC4LCMG7164 |
| 4UZADVFC0LCMG4293 | 4UZADVFC1MCMG7169 | 4UZADVFC2MCMG7178 | 4UZADVFC3MCMG7190 | 4UZADVFC4MCMG7179 |
| 4UZADVFC0LCMG4309 | 4UZADVFC1MCMG7172 | 4UZADVFC2MCMG7181 | 4UZADVFC4KCKL9345 | 4UZADVFC4MCMG7182 |
| 4UZADVFC0LCMG4312 | 4UZADVFC2KCKL9344 | 4UZADVFC2MCMG7195 | 4UZADVFC4KCKL9359 | 4UZADVFC4MCMG7196 |
| 4UZADVFC0MCMG7177 | 4UZADVFC2KCKL9358 | 4UZADVFC3KCKL9367 | 4UZADVFC4KCKL9362 | 4UZADVFC5KCKS0142 |
| 4UZADVFC6KCKS0151 | 4UZADVFC7LCLW2851 | 4UZADVFC8LCLW2860 | 4UZADVFC9LCLW2849 | 4UZADVFCXLCW2861  |
| 4UZADVFC6KCKS0165 | 4UZADVFC7LCLW2865 | 4UZADVFC8LCLW2874 | 4UZADVFC9LCLW2852 | 4UZADVFCXLCW2875  |
| 4UZADVFC6LCLW2856 | 4UZADVFC7LCMA0784 | 4UZADVFC8LCMA0776 | 4UZADVFC9LCLW2866 | 4UZADVFCXLCMA0777 |
| 4UZADVFC6LCLW2873 | 4UZADVFC7LCMD3896 | 4UZADVFC8LCMA0793 | 4UZADVFC9LCMA0785 | 4UZADVFCXLCMA0780 |
| 4UZADVFC6LCMA0775 | 4UZADVFC7LCMD3901 | 4UZADVFC8LCMC9145 | 4UZADVFC9LCMD3897 | 4UZADVFCXLCMA0794 |
| 4UZADVFC6LCMA0789 | 4UZADVFC7LCME5045 | 4UZADVFC8LCMD3888 | 4UZADVFC9LCMD3902 | 4UZADVFCXLCMC9146 |
| 4UZADVFC6LCMA0792 | 4UZADVFC7LCME5059 | 4UZADVFC8LCMD3891 | 4UZADVFC9LCME5046 | 4UZADVFCXLCMD3889 |
| 4UZADVFC6LCMC9144 | 4UZADVFC7LCME5062 | 4UZADVFC8LCME5054 | 4UZADVFC9LCME5063 | 4UZADVFCXLCMD3892 |
| 4UZADVFC6LCMD3887 | 4UZADVFC7LCMG4291 | 4UZADVFC8LCME5068 | 4UZADVFC9LCMG4289 | 4UZADVFCXLCME5055 |
| 4UZADVFC6LCMD3890 | 4UZADVFC7LCMG4307 | 4UZADVFC8LCMG4297 | 4UZADVFC9LCMG4292 | 4UZADVFCXLCMG4298 |
| 4UZADVFC6LCME5053 | 4UZADVFC7LCMG4310 | 4UZADVFC8LCMG4302 | 4UZADVFC9LCMG4308 | 4UZADVFCXLCMG4303 |

|                   |                   |                   |                   |                   |
|-------------------|-------------------|-------------------|-------------------|-------------------|
| 4UZADVFC6LCME5067 | 4UZADVFC7MCMG7175 | 4UZADVFC8LCMG7166 | 4UZADVFC9LCMG4311 | 4UZADVFCXLCMG7167 |
| 4UZADVFC6LCMG4296 | 4UZADVFC7MCMG7192 | 4UZADVFC8MCMG7170 | 4UZADVFC9MCMG7176 | 4UZADVFCXMCMG7168 |
| 4UZADVFC6LCMG4301 | 4UZADVFC8KCKL9350 | 4UZADVFC8MCMG7184 | 4UZADVFC9MCMG7193 | 4UZADVFCXMCMG7171 |
| 4UZADVFC6LCMG7165 | 4UZADVFC8KCKS0118 | 4UZADVFC9KCKL9342 | 4UZADVFCXKCKL9348 | 4UZADVFCXMCMG7185 |
| 4UZADVFC7KCKS0112 | 4UZADVFC8KCKS0121 | 4UZADVFC9KCKL9356 | 4UZADVFCXKCKL9351 | 4UZADVFC7LCLW2848 |
| 4UZADVFC7KCKS0143 | 4UZADVFC8KCKS0149 | 4UZADVFC9KCKS0113 | 4UZADVFCXKCKS0119 | 4UZADVFC8LCLW2857 |
| 4UZADVFC7KCKS0157 | 4UZADVFC8KCKS0152 | 4UZADVFC9KCKS0144 | 4UZADVFCXKCKS0153 | 4UZADVFC9KCKS0161 |
| 4UZADVFC7KCKS0160 | 4UZADVFC8KCKS0166 | 4UZADVFC9KCKS0158 | 4UZADVFCXKCKS0167 | 4UZADVFCXLCLW2858 |
| 4UZADVFC5KCKS0156 | 4UZADVFC5LCMC9149 | 4UZADVFC5LCME5044 | 4UZADVFC5LCMG4306 | 4UZADVFC6KCKS0103 |
| 4UZADVFC5LCLW2847 | 4UZADVFC5LCMC9152 | 4UZADVFC5LCME5058 | 4UZADVFC5MCMG7174 | 4UZADVFC6KCKS0117 |
| 4UZADVFC5LCLW2850 | 4UZADVFC5LCMD3895 | 4UZADVFC5LCME5061 | 4UZADVFC5MCMG7191 | 4UZADVFC6KCKS0120 |
| 4UZADVFC5LCLW2864 | 4UZADVFC5LCMD3900 | 4UZADVFC5LCMG4290 | 4UZADVFC6KCKL9346 | 4UZADVFC6KCKS0148 |

### Verona VIN #s – 23 Total (Shipped)

|                   |                   |                   |
|-------------------|-------------------|-------------------|
| 1FVACYFEXKHL6290  | 1FVACYFE6KHKR3828 | 1FVACYFE9KHL6247  |
| 1FVACYFE5KHKR3822 | 1FVACYFE3KHL6275  | 1FVACYFE9KHL6233  |
| 1FVACYFE4KHKR3830 | 1FVACYFE1KHL6324  | 1FVACYFE5KHKR3836 |
| 1FVACYFE7KHL6330  | 1FVACYFE8KHKR3829 | 1FVACYFE7KHL6246  |
| 1FVACYFE1KHL6260  | 1FVACYFE3KHL6325  | 1FVACYFE6LHLL8610 |
| 1FVACYFE0KHL6234  | 1FVACYFE2KHL6266  | 3ALACYFE7DLL8458  |
| 1FVACYFE9KHKR3824 | 1FVACYFE0KHL6282  | 3ALACYFE5MDMN3688 |
| 1FVACYFE4KHL6320  | 1FVACYFE0KHKR3825 |                   |

### Verona LE VIN #s

|                   |
|-------------------|
| 1FVACYFE8LHKY8373 |
|-------------------|

### Garage Unit VIN #s

|                   |
|-------------------|
| 3ALHGBDV6LSKY8523 |
|-------------------|

### Classic VIN #s – 18 Total (Shipped)

|                   |                   |                   |                   |
|-------------------|-------------------|-------------------|-------------------|
| 3ALAGBDV8JSJU7564 | 3ALHGBDV2LDKU9240 | 3ALAGBDV6KDKG0379 | 3ALHGED1XLDLG6882 |
| 3ALHGBDV2KDKN2640 | 3ALHGED15LDKR1836 | 3ALAGBDV2KDKG0377 | 3ALHGED12LDMD3944 |
| 3ALHGED19KDKG0440 | 5KKHBLD16KLKF9010 | 4V5WC9EJ8LN213499 | 5KKHBLD19MLMK3647 |
| 4V5NC9EJ4JN894527 | 5KKHBLD17KLKV0109 | 3ALHGBDV6LDKU9239 | 5KKHBLD12LLLL4033 |
| 3ALHGBDV9KDKN3235 | 4V5NC9EJ4JN894530 |                   |                   |

### Production Dates:

Begin: November of 2018  
End: July of 2020

### Description

#### Describe The Defect:

In some RV's or in some cases a boat that have an R1731 or R2131 or S31 "cooking stove" installed, a gas leak may occur at the joint between the gas saddle valve for the burners and the manifold under the burner surface.

**Provide applicable FMVSS:**

N/A

**Provide further FMVSS affected:**

None.

**Describe the cause:**

Dometic states that these leaks are a result of field adjustment and overtightening of securement bolt for the saddle valve to manifold connection.

**Describe the risk:**

After an install or usage period of 3-6 months, the installer, occupant, or user of the appliance smells gas and apparently attempts to tighten the securement bolts that hold one or more of the stove saddle valves in place and sealed to the manifold. This action may result in the overtightening of the securement bolt for the saddle valve which may cause damage to the o-ring seal between the saddle valve and the manifold resulting in a continuous gas leak that is readily detectable from the smell. Dometic has had one instance of ignition and damage to the piezo igniter and one control knob, although the ignition was contained within the stove enclosure.

**Identify any warning which can precede or occur:**

None.

**Chronology Determination**

**Provide the chronology of events:**

On September 29, 2020, **Renegade RV** received an Owner Notice letter by Dometic about recall 20E071 for their R1731, R2131 and S31 series "cooking stoves".

On September 30, 2020 it was agreed that **Renegade RV** should file a Part 573.

**Identify the Remedy**

**Describe the remedy program:**

Dometic is working on, but has not identified, a remedy for this potential defect at this time, but will advise customers when a remedy kit is available

**Describe what distinguishes the remedy component:**

None.

**Identify and describe how and when the condition was corrected in production:**

The remedy will consist of 1) instructions 2) remedy kit 3) Recall Response Card to be filled out and returned at the time of remedy application. Dometic will be supplying this recall remedy at no charge.