



NUMBER: 08-084-20

GROUP: 08 - Electrical

DATE: September 25, 2020

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.

This Technical Service Bulletin (TSB) has also been released as a Rapid Response Transmittal (RRT) 20-059, date of issue September 25, 2020. All applicable Sold and Un-Sold RRT VINs have been loaded. To verify this RRT service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library. All repairs are reimbursable within the provisions of warranty. This RRT will expire 18 months after the date of issue.

SUBJECT:

Flash: Battery Pack Control Module (BPCM) Updates - AN-K8PHEV-18-20200904

OVERVIEW:

Refer to China Joint Venture (JV) released document AN-K8PHEV-18-20200904, for details on this service action.

MODELS:

2019 (K8) Jeep Grand Commander (China)

NOTE: This bulletin applies to vehicles within the following markets/countries: APAC (China only).

NOTE: This bulletin applies to vehicles equipped with a 2.0L I4 DOHC DI Turbo PHEV Engine (Sales Code ECX).

NOTE: Other modules are required to be flashed for this update to be effective, the following modules are all to be updated along with this BPCM update:

- Power Inverter Module (PIM)
- Powertrain Control Module (PCM)

Policy:

Information Only