



**NUMBER:** 08-087-20

**GROUP:** 08 - Electrical

**DATE:** September 29, 2020

*This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.*

This Technical Service Bulletin (TSB) has also been released as a Rapid Response Transmittal (RRT) 20-065, date of issue September 29, 2020. All applicable Sold and Un-Sold RRT VINs have been loaded. To verify this RRT service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library. All repairs are reimbursable within the provisions of warranty. This RRT will expire 18 months after the date of issue.

**SUBJECT:**

Flash: Power Inverter Module (PIM) Updates - AN-K8PHEV-18-20200927

**OVERVIEW:**

Refer to China Joint Venture (JV) released document AN-K8PHEV-18-20200927, for details on this service action.

**MODELS:**

2020 (K8) Jeep Grand Commander (China)

**NOTE:** This bulletin applies to vehicles within the following markets/countries: APAC (China only).

**NOTE:** This bulletin applies to vehicles built on or before August 30, 2020 (MDH 0830XX) equipped with a 2.0L I4 DOHC DI Turbo PHEV Engine (Sales Code ECX).

**NOTE:** Other modules are required to be flashed for this update to be effective, the following modules are all to be updated along with this PIM update:

- Battery Pack Control Module (BPCM)
- Powertrain Control Module (PCM)

**Policy:**

Information Only