

Daimler Trucks
North America LLC

Freightliner Custom Chassis
552 Hyatt Street
Gaffney, SC 29341
800-385-4357 – Phone
Fccservice@Daimler.com

October 2020

Subject: Steering Shaft Pinch Bolt on MC Chassis

Freightliner Custom Chassis has determined that the wrong size pinch bolt may have been installed in the steering shaft on your vehicle. This notice is not considered safety related, but rather a customer notification and recommendation that it be repaired.

Authorized Freightliner Dealers and Service Centers will inspect and, if needed, install the correct hardware. Please contact your local dealer before the expiration date of this notice to schedule an appointment to have this work performed.

This work will be performed at no charge if completed before **October 31, 2021**. Please direct any questions to Freightliner Custom Chassis at 800-FTL-HELP (800-385-4357) or alternatively, you may send an email to Fccservice@daimler.com.

Thank You

Freightliner Custom Chassis