

Subject Elimination of front underbody holes		Market USA
Service Category Vehicle Exterior	Section Exterior Panels/Trim	
Applicability (MY20 - MY21 - Highlander)		

APPLICABLE VEHICLES

2021	Highlander
------	------------

CONDITION

Beginning with the 2021MY, Highlander models no longer have front underbody holes and therefore do not require the installation of body plugs. The rear underbody holes still require the installation of body plugs at the time of Pre-Delivery inspection / Service.



Picture 1:
Previous condition: Hole present

RECOMMENDATIONS

No repair needed.

LINK REFERENCES

This Tech Tip does not contain any link references

[Click here to enter text.](#)