

PREVOST PRODUCT CHANGE NOTICE

MP-1000 OBSOLESCENCE



	H3-45		X3-45			
	Coach	VIP	Coach	Plattsburgh	VIP	VIP Ent.
From VIN	L-1093	L-1093	L-6625	L-7745	L-6625	L-6625

ECN :2019152 rev:

DESCRIPTION: Replacement of the MP-1000 Safety Messaging player from REI with the new MP-1200HD

SYSTEM:
ENTERTAINMENT

MODIFICATION: Modification of the option to replace MP-1000 with an MP-1200HD

REASONS (WHY): Obsolescence of the MP-1000

BENEFITS:

- Up to 1080P HD Features

IMPACT FOR CUSTOMER:

- Coach need to be wired with HHED cables

RETROFIT AND AFTERMARKET SERVICES:

- New part number #901809 , The MP-1200 can be mounted in the same holes as the MP-1000 by installing the brackets from the interior.
The MP-1200 is wider and use a different cable.

