

# PREVOST PRODUCT CHANGE NOTICE

## XENON LIGHT OBSOLESCENCE



From VIN	H3-45		X3-45			
	Coach	VIP	Coach	Plattsburgh	VIP	VIP Ent.
	M-1162	M-1156	N/A	N/A	N/A	N/A

ECN :2020077

**DESCRIPTION:** CANCEL OF XENON HEADLIGHT OPTION

**SYSTEM:**  
**ELECTRICAL**

**MODIFICATION:** The option of the Xenon Headlight type D2S is no longer available and need to be replaced with Halogens Headlight

**REASONS (WHY):** Supplier (OSRAM) can no longer provide material to produce Xenon Headlight

**BENEFITS:**

- NO BENIFITS

**IMPACT FOR CUSTOMER:**

- Remaining inventory is dedicated for after market
- In the event of supply shortage, customer must change the headlight for Halogen type
- Recommendation of adding LED fog lights to increase the light output.

**RETROFIT AND AFTERMARKET SERVICES:**

- ROAD SIDE 930010 replace 930013
- CURBSIDE 930011 replace 930014

