

WLF0 Workshop campaign - Re-programming PDK control unit

Version 1

Responsible: Michael Zimmermann (VAQ4)

English (GB)

- > [Overview](#)
- > [Required software](#)
- > [Warranty processing](#)
- > [Porsche Mobility](#)
- > [Further information](#)

WLF0 Workshop campaign - Re-programming PDK control unit

Overview

The PDK control unit on the affected vehicles was programmed using an outdated software version. To ensure that the PDK control unit software corresponds to the latest version, the software for the PDK control unit must be updated.

Model type	Panamera 4 E-Hybrid Sport Turismo (971) Panamera 4S (971) / Panamera 4S Sport Turismo (971) Panamera Turbo (971) / Panamera Turbo Sport Turismo (971) Panamera Turbo S E-Hybrid (971) / Panamera Turbo S E-Hybrid Sport Turismo (971)
Model year	2017-2018
Number	21

Required software

PIWIS Tester 3 test software version	Version 39.700.030 (or higher)
--------------------------------------	--------------------------------

If other programming campaigns that affect the same control unit and involve the identical procedure are open for a vehicle in addition to this campaign, the affected control unit must only be programmed once using the current PIWIS Tester test software. For these cases, please proceed as follows for the campaigns that have not been carried out:

- Mark the campaign as 'cannot be carried out' with the reason "Modification of the affected component" in PQIS. The "Warranty relevance" flag must be activated in order to be able to set a warranty claim and close the campaign.
- A warranty claim must be submitted for the campaign in which 0 TU is entered as the specified working time and no material items are specified.

Warranty processing

Validity:

This workshop campaign will be carried out up to 21.10.2025 and will be closed by the specified date. Please note that warranty claims can only be processed before this date.

Scope 1:

Damage Code	WLF0 66 000
Repair Code	1
Working time	80 TU

Please enter the campaign that was carried out in the Warranty and Maintenance booklet for the vehicle.

Porsche Mobility

If requested, the mobility of the affected customer can be assured by offering a suitable replacement vehicle.

Please invoice this additional service with the campaign scope via WWS.

Further information

Work instruction	TI No. 76/20, Group 3, Service, WLF0
Vehicle list and allocation	See PCSS or attached VIN list for reference
Technical Information*	See PCSS or the Aftersales Document Database for reference

[WLF0 VIN List.xlsx](#)

8.6 KB

(40 views)

Created by [Ryan Cooney](#) on Nov 13, 2020 4:37 PM. Last modified by [Ryan Cooney](#) on Nov 13, 2020 4:42 PM.

558 Views [Report Abuse](#)

Categories: Panamera, Workshop Campaigns

Tags: [panamera](#), [971](#), [workshop campaign](#), [mj l](#), [wlf0](#)

Content and Topics

Personal

Manage

Create

- Your Groups >
- Your Content >
- Your Places >
- Edit Profile >
- Change Password >
- Admin Console >
- PPN Administration >
- Discussion >
- Files >
- Document >
- Collaboration >
- Document
- Blog Post >
- Poll >
- Event >
- Photo Album >
- Idea >
- Space >
- Group >

© 2020 Dr. Ing. h.c. F. Porsche AG. Legal notice. Copyright. Terms of use. Privacy Policy. Cookie Policy. [010](#)