



SERVICE BULLETIN

Vac-Tron Equipment, LLC

Trenchless
Okahumpka, FL 34762 USA

**FIELD CAMPAIGN
SERVICE BULLETIN #**

SVV2020-015

DATE: 05 November 2020

**CAMPAIGN
TYPE:**

Mandatory

**CAMPAIGN
CATEGORY:**

Kit and Bulletin

DEALER INSTALLATION ONLY

MACHINE / ATTACHMENT MODEL(S):	Serial Numbers		Kit Version
	Included	Excluded	
2015 LP873SDT HVY	2170 – 2180	N/A	VVK01
2016 LP873SDT HVY	2103 – 2190		
2017 LP873SDT HVY	2102 – 2353		
2018 LP873SDT HVY	2101 – 2380		
2019 LP873SDT HVY	2109 – 2378		
2019 LPSDT HVY	2026 – 2084		

Subject: Rear Extension Replacement. (VVK000013).

Background: The rear extension supplied with VVK000001 may have interference with the debris tank door and cause door damage.

Solution: VVK000013 has been created to provide the necessary parts and instructions to replace the rear extension.

WARRANTY CONSIDERATION:

1. Warranty will pay for parts and 2.0 hour's labor. Use warranty labor code SB20 when filing a claim. Reference this Service Bulletin.

- **DEADLINE** to receive reimbursement for parts and labor is: **October 31, 2021**

2. Other allowance [If Appropriate (Travel, etc.)]

- **DEADLINE** to receive travel allowance is: **Month Day, Year**

<p>Completion Schedule:</p> <p><input type="checkbox"/> Product Safety Alert: Install Immediately</p> <p><input type="checkbox"/> 90 Days from <u>MM/DD/YYYY</u></p> <p><input type="checkbox"/> 180 Days from <u>MM/DD/YYYY</u></p> <p><input checked="" type="checkbox"/> 1 Year from 10/30/2020</p> <p><input type="checkbox"/> Only Units within Standard Limited Warranty Period</p> <p><input type="checkbox"/> N/A</p>	<p>Reimbursement:</p> <p><input type="checkbox"/> Product Safety Alert:</p> <p style="padding-left: 20px;">Work Completion Certificate Required</p> <p><input checked="" type="checkbox"/> All Units Listed Above</p> <p style="padding-left: 20px;"><input checked="" type="checkbox"/> Parts <input checked="" type="checkbox"/> Labor Paid (Labor Code: SB20)</p> <p><input type="checkbox"/> Only Units within Standard Limited Warranty Period</p> <p><input type="checkbox"/> No Reimbursement</p>
--	--

<p>Internal Reference:</p> <p>TREAD Act Code <i>(Choose one or more codes applicable)</i></p>	<input checked="" type="checkbox"/>	--	Not Applicable	<input type="checkbox"/>	12	Exterior lighting
	<input type="checkbox"/>	02	Suspension	<input type="checkbox"/>	16	Structure
	<input type="checkbox"/>	03	Service brake system, hydraulic	<input type="checkbox"/>	17	Latch
	<input type="checkbox"/>	04	Service brake system, air	<input type="checkbox"/>	19	Tires
	<input type="checkbox"/>	05	Parking brake	<input type="checkbox"/>	20	Wheels
	<input type="checkbox"/>	11	Electrical	<input type="checkbox"/>	21	Trailer hitch

<p>Dealer Distribution:</p> <p><input type="checkbox"/> Domestic</p> <p><input type="checkbox"/> International</p> <p><input checked="" type="checkbox"/> Both</p>
--

AFFECTED MACHINES WITHIN SERIAL NUMBER RANGE IDENTIFIED ON PAGE 1 OF THIS SERVICE BULLETIN

MODEL	VIN	SERIAL/UNIT	MODEL	VIN	SERIAL/UNIT
LP873SDT	5HZBF192XFLLF2170	151269	LP873SDT	5HZBF392XHLEH2353	171178
LP873SDT	5HZBF1921FLLF2171	151272	LP873SDT	5HZBF192XHLEH2170	171179
LP873SDT	5HZBF1923FLLF2172	151273	LP873SDT	5HZBF1927HLEH2160	171187
LP873SDT	5HZBF1923FLMF2174	151274	LP873SDT	5HZBF1924HLDH2145	171193
LP873SDT	5HZBF1925FLMF2175	151277	LP873SDT	5HZBF1926HLDH2146	171194
LP873SDT	5HZBF1927GLMF2177	161018	LP873SDT	5HZBF192XHLDH2148	171195
LP873SDT	5HZBF1929GLMF2178	161019	LP873SDT	5HZBF1921HLDH2149	171196
LP873SDT	5HZBF1920GLMF2179	161020	LP873SDT	5HZBF192XHLEH2167	171230
LP873SDT	5HZBF1927GLMF2180	161021	LP873SDT	5HZBF1921HLEH2168	171231
LP873SDT	5HZBF1927GLAG2103	161036	LP873SDT	5HZBF1922HLDH2144	171234
LP873SDT	5HZBF1920GLAG2105	161042	LP873SDT	5HZBF1921HLGH2175	171235
LP873SDT	5HZBF1929GLBG2106	161043	LP873SDT	5HZBF1929HLEH2161	171269
LP873SDT	5HZBF1920GLBG2107	161044	LP873SDT	5HZBF1929HLEH2158	171303
LP873SDT	5HZBF1926GLBG2113	161064	LP873SDT	5HZBF192XHLGH2188	171315
LP873SDT	5HZBF1928GLBG2114	161065	LP873SDT	5HZBF1921HLGH2189	171323
LP873SDT	5HZBF192XGLCG2117	161077	LP873SDT	5HZBF1923HLHH2195	171340
LP873SDT	5HZBF1925GLDG2125	161115	LP873SDT	5HZBF1925HLHH2196	171341
LP873SDT	5HZBF1927GLDG2126	161116	LP873SDT	5HZBF1922HLJH2202	171352
LP873SDT	5HZBF1921GLFG2149	161182	LP873SDT	5HZBF1927HLHH2197	171363
LP873SDT	5HZBF1927GLFG2150	161185	LP873SDT	5HZBF1929HLHH2198	171364
LP873SDT	5HZBF1929GLFG2151	161188	LP873SDT	5HZBF192XHLJH2206	171424
LP873SDT	5HZBF1920GLFG2152	161189	LP873SDT	5HZBF1924HLKH2222	171490
LP873SDT	5HZBF1922GLFG2153	161204	LP873SDT	5HZBF1929HLKH2216	171495
LP873SDT	5HZBF1922GLHG2160	161243	LP873SDT	5HZBF1922HLKH2218	171499
LP873SDT	5HZBF1922GLJG2171	161280	LP873SDT	5HZBF1924HLKH2219	171503
LP873SDT	5HZBF1928GLKG2176	161304	LP873SDT	5HZBF1923HLLH2229	171528
LP873SDT	5HZBF1921GLLG2183	161352	LP873SDT	5HZBF192XHLLH2230	171529
LP873SDT	5HZBF1925HLLG2186	171009	LP873SDT	5HZBF1922HLLH2237	171556
LP873SDT	5HZBF1923HLLG2185	171010	LP873SDT	5HZBF1920HLMH2238	171559
LP873SDT	5HZBF1927HLLG2187	171011	LP873SDT	5HZBF1922HLMH2239	171569
LP873SDT	5HZBF1929HLLG2188	171012	LP873SDT	5HZBF1922JLAJ2107	181043
LP873SDT	5HZBF1920HLLG2189	171013	LP873SDT	5HZBF1921JLBJ2117	181058
LP873SDT	5HZBF1927HLLG2190	171014	LP873SDT	5HZBF1923JLBJ2118	181059
LP873SDT	5HZBF1929HLAH2102	171032	LP873SDT	5HZBF1920JLBJ2111	181063
LP873SDT	5HZBF1920HLAH2103	171033	LP873SDT	5HZBF1922JLBJ2112	181064
LP873SDT	5HZBF1923HLAH2113	171077	LP873SDT	5HZBF1927JLBJ2123	181094
LP873SDT	5HZBF1920HLBH2119	171084	LP873SDT	5HZBF1929JLDJ2162	181109
LP873SDT	5HZBF1929HLBH2121	171092	LP873SDT	5HZBF1928JLCJ2134	181138
LP873SDT	5HZBF1920HLBH2122	171093	LP873SDT	5HZBF1927JLDJ2158	181173
LP873SDT	5HZBF1927HLBH2120	171104	LP873SDT	5HZBF1928JLCJ2151	181191
LP873SDT	5HZBF1922HLCH2125	171119	LP873SDT	5HZBF192XJLCJ2152	181194
LP873SDT	5HZBF1928HLDH2147	171159	LP873SDT	5HZBF1921JLCJ2153	181195
LP873SDT	5HZBF1924HLCH2126	171161	LP873SDT	5HZNF1929JLEJ2178	181206
LP873SDT	5HZBF1926HLCH2127	171162	LP873SDT	5HZBF1925JLDJ2160	181217
LP873SDT	5HZBF1921HLEH2154	171170	LP873SDT	5HZBF1927JLEJ2163	181233

AFFECTED MACHINES WITHIN SERIAL NUMBER RANGE IDENTIFIED ON PAGE 1 OF THIS SERVICE BULLETIN

MODEL	VIN	SERIAL/UNIT	MODEL	VIN	SERIAL/UNIT
LP873SDT	5HZBF1920JLEJ2179	181249	LP873SDT	5HZBF1924JLGJ2241	181485
LP873SDT	5HZBF1929JLDJ2159	181253	LP873SDT	5HZBF1926JLGJ2242	181487
LP873SDT	5HZBF1922JLEJ2202	181257	LP873SDT	5HZBF1928JLGJ2243	181488
LP873SDT	5HZBF1924JLEJ2203	181279	LP873SDT	5HZBF192XJLGJ2244	181489
LP873SDT	5HZBF1926JLEJ2204	181282	LP873SDT	5HZBF1921JLGJ2245	181490
LP873SDT	5HZBF1926JLEJ2171	181283	LP873SDT	5HZBF1927JLHJ2284	181506
LP873SDT	5HZBF1928JLEJ2172	181291	LP873SDT	5HZBF1929JLHJ2285	181507
LP873SDT	5HZBF1922JLEJ2166	181293	LP873SDT	5HZBF192XJLHJ2280	181508
LP873SDT	5HZBF1929JLEJ2200	181294	LP873SDT	5HZBF1921JLHJ2281	181509
LP873SDT	5HZBF192XJLEJ2173	181295	LP873SDT	5HZBF1920JLHJ2269	181527
LP873SDT	5HZBF1921JLEJ2174	181296	LP873SDT	5HZBF1928JLHJ2262	181528
LP873SDT	5HZBF1926JLEJ2168	181298	LP873SDT	5HZBF1927JLJ2295	181552
LP873SDT	5HZBF1928JLEJ2169	181299	LP873SDT	5HZBF1920JLJ2302	181560
LP873SDT	5HZBF1923JLEJ2175	181302	LP873SDT	5HZBF1922JLJ2303	181562
LP873SDT	5HZBF1925JLEJ2176	181303	LP873SDT	5HZBF1923JLJ2309	181579
LP873SDT	5HZBF1927JLEJ2177	181310	LP873SDT	5HZBF192XJLJ2310	181580
LP873SDT	5HZBF1927JLEJ2180	181311	LP873SDT	5HZBF1921JLJ2311	181581
LP873SDT	5HZBF1929JLEJ2181	181312	LP873SDT	5HZBF1923JLJ2312	181582
LP873SDT	5HZBF1920JLEJ2182	181313	LP873SDT	5HZBF1928JLJ2306	181585
LP873SDT	5HZBF1922JLEJ2183	181314	LP873SDT	5HZBF1924JLKJ2323	181586
LP873SDT	5HZBF1926JLEJ2185	181319	LP873SDT	5HZBF1926JLKJ2324	181587
LP873SDT	5HZBF1928JLEJ2186	181323	LP873SDT	5HZBF1928JLKJ2325	181595
LP873SDT	5HZBF192XJLEJ2187	181324	LP873SDT	5HZBF192XJLKJ2326	181596
LP873SDT	5HZBF1921JLEJ2188	181325	LP873SDT	5HZBF192XJLMJ2378	181644
LP873SDT	5HZBF1927JLEJ2194	181334	LP873SDT	5HZBF1925JLKJ2346	181652
LP873SDT	5HZBF1924JLEJ2198	181374	LP873SDT	5HZBF1921JLJ2292	181655
LP873SDT	5HZBF1923JLEJ2211	181377	LP873SDT	5HZBF1923JLJ2293	181656
LP873SDT	5HZBF1925JLGJ2247	181385	LP873SDT	5HZBF1927JLKJ2316	181657
LP873SDT	5HZBF1923JLGJ2246	181386	LP873SDT	5HZBF1927JLKJ2347	181671
LP873SDT	5HZBF1925JLEJ2212	181395	LP873SDT	5HZBF1921JLKJ2330	181672
LP873SDT	5HZBF1929JLFJ2216	181400	LP873SDT	5HZBF1923JLKJ2331	181673
LP873SDT	5HZBF1920JLFJ2217	181401	LP873SDT	5HZBF1925JLKJ2332	181674
LP873SDT	5HZBF1927JLFJ2215	181436	LP873SDT	5HZBF1927JLKJ2333	181675
LP873SDT	5HZBF192XJLGJ2230	181437	LP873SDT	5HZBF1924KLBK2142	191001
LP873SDT	5HZBF1921JLGJ2231	181438	LP873SDT	5HZBF1925KLLJ2352	191022
LP873SDT	5HZBF1927JLGJ2248	181453	LP873SDT	5HZBF1929KLLJ2354	191031
LP873SDT	5HZBF1925JLHJ2283	181475	LP873SDT	5HZBF1920KLLJ2355	191032
LP873SDT	5HZBF1925JLGJ2233	181477	LP873SDT	5HZBF1928KLLJ2362	191051
LP873SDT	5HZBF1927JLGJ2234	181478	LP873SDT	5HZBF192XKLLJ2363	191062
LP873SDT	5HZBF192XJLHJ2263	181479	LP873SDT	5HZBF1925KLAK2129	191077
LP873SDT	5HZBF1920JLGJ2236	181480	LP873SDT	5HZBF1921KLAK2130	191078
LP873SDT	5HZBF1922JLGJ2237	181481	LP873SDT	5HZBF1923KLAK2131	191079
LP873SDT	5HZBF1924JLGJ2238	181482	LP873SDT	5HZBF1927KLLJ2334	191080
LP873SDT	5HZBF1926JLGJ2239	181483	LP873SDT	5HZBF1929KLLJ2335	191081
LP873SDT	5HZBF1922JLGJ2240	181484	LP873SDT	5HZBF1920KLLJ2336	191082

AFFECTED MACHINES WITHIN SERIAL NUMBER RANGE IDENTIFIED ON PAGE 1 OF THIS SERVICE BULLETIN

MODEL	VIN	SERIAL/UNIT
LP873SDT	5HZBF192XKLAK2109	191126
LP873SDT	5HZBF1923KLKJ2329	191132
LP873SDT	5HZBF1922KLKJ2337	191135
LP873SDT	5HZBF1924KLKJ2338	191140
LP873SDT	5HZBF1925KLAK2101	191145
LPSDT	5HZG19212KK002041	191150
LPSDT	5HZG19214KK002042	191151
LP873SDT	5HZBF1922KLAK2136	191156
LP873SDT	5HZBF1928KLMJ2364	191157
LP873SDT	5HZBF1926KLMJ2380	191158
LP873SDT	5HZBF1928KLAK2139	191211
LPSDT	5HZG26215KK002076	191279
LPSDT	5HZG19212KK002024	191297
LPSDT	5HZG1921XKK002031	191341
LPSDT	5HZG19211KK002032	191342
LPSDT	5HZG19219KK002036	191346
LPSDT	5HZG19210KK002068	191381
LPSDT	5HZG19212KK002069	191382
LPSDT	5HZG19219KK002070	191383
LPSDT	5HZG19210KK002071	191384
LPSDT	5HZG19217KK002049	191391
LPSDT	5HZG19212KK002055	191399
LPSDT	5HZG19216KK002057	191404
LPSDT	5HZG19218KK002058	191405
LPSDT	5HZG19211KK002080	191464
LPSDT	5HZG19215KK002082	191465
LPSDT	5HZG19219KK002084	191467
LPSDT	5HZJ16238KK002034	191504