

## TECHNICAL TOPICS

### BODY



Secondary Door Seal Loose	19-20 MY Discovery Sport
<p><u>Customer Voice:</u></p> <ul style="list-style-type: none"><li>- A customer may report that the secondary door seal is coming loose or does not fit the properly around the door opening.</li></ul> <p><u>Technical Description:</u></p> <ul style="list-style-type: none"><li>- The secondary door seal may not be retained properly on the body opening flange.</li></ul> <p><u>Status:</u></p> <ul style="list-style-type: none"><li>- Engineering is currently investigating this concern.</li><li>- Please submit an EPQR with pictures for any cases of customer complaints that you find for this concern.</li><li>- Measurements of the body flange thickness may be required to identify root cause of the concern.</li></ul>	

