

Classification:

EL16-029a

Reference:

ITB16-031a

 COPYRIGHT© NISSAN NORTH AMERICA, INC.
 Date:

December 18, 2020

2016 QX60; AUTOMATIC BACK DOOR CALIBRATION PROCEDURE

APPLIED VEHICLE: 2016 QX60 (L50)
 2016 QX60 Hybrid (L50)

This bulletin is no longer active.

Please discard previous versions of ITB16-031.

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
August 5, 2016	ITB16-031	Original bulletin published
December 18, 2020	ITB16-031a	Bulletin no longer active

Infiniti Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Infiniti retailer to determine if this applies to your vehicle.