

## GPOP - Issue Review System

**Part Number:** 68321288A\$, 68321289A\$, 68321316A\$, 68321317A\$, 68321334A\$, 68321335A\$, 68321314A\$, 68321315A\$, 68321336A\$, 68321337A\$, 68321324A\$, 68321325A\$, 68314748A\$, 68314749A\$, 68374972A\$, 68374973A\$, 68043884A\$, 68043885A\$, 68376200A\$, 68376201A\$, 68103996A\$, 68103997A\$, 68143986A\$, 68143987A\$, 68103998A\$, 68103999A\$, 68143989A\$, 68171818A\$, 68171819A\$, 68171824A\$, 68171825A\$, 68171826A\$, 68171827A\$, 68314750A\$, 68314751A\$, 68143988A\$, 68044804A\$, 68044805A\$, 68045132A\$, 68045133A\$, 68045134A\$, 68045135A\$

**Part Description:** Power Window Regulator or Motor

**Issue** Owners may complain that the Driver and or Passenger Windows are inoperative.

**Description:** Technician may find DTC's B18BA-12 - Window Control - Circuit Short to Battery, B18BA-13 - Window Control - Circuit Open (stored or active).~

Replace the DDM or PDM per detailed repair information in Service Library or reference Star Online Publication S2008000182. Replacing regulators or motors will not correct this issue.

~  
Contact us at [CAGRIS@Chrysler.com](mailto:CAGRIS@Chrysler.com) for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.