

## GPOP - Issue Review System

**Part Number:** 68493535A\$

**Part Description:** MODULE, Body Controller, Telematics

**Issue Description:** If the BCM is being replaced due to a confirmed/reported Low Beam Headlight Out message, and the headlights are functional, please refer to SOL Publication S2008000125. Per the SOL, software is being developed to address the issue and component replacement will not resolve this issue.

~ \_\_\_\_\_ ~  
Contact us at [CAGRIS@Chrysler.com](mailto:CAGRIS@Chrysler.com) for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.

