



STAR ONLINE PUBLICATION

Case Number: S1907000001

Release Date: 07/23/2020

Symptom/Vehicle Issue: Skunk Like Smell From The Engine Compartment Area

Customer complaint/ technician observation: Owner complains that they smell a skunk like odor in the cabin and externally in the front of the vehicle; engine compartment. Technician has identified a smell that is similar to a skunk upon inspection.

Discussion: Some trucks may have been built with a fan/shroud module assembly that emits an odor similar to a skunk as the vehicle warms. If the vehicle has less than 5000 miles and is still exhibiting this distinct odor, and it is defined as coming from the vehicle, replace the fan module assembly only. Vehicles do not require radiator hoses or other components.

Replacement Part 68268606AD (850W) for engine sales code EXH, EZH, EZL
Replacement Part 68275634AC for sales code ERG

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found