

WLN5 Workshop campaign – Reworking screws on front side member

Version 2

WLN5 Workshop campaign – Reworking screws on front side member

Overview

There is a possibility that a screw on the front side member was not tightened to the prescribed tightening torque on the affected vehicles.

As a result, the screw can become loose while driving, resulting in noises from around the front body section.

To prevent this from happening, the fastening screws on the side member must be tightened to the prescribed tightening torque.

Please arrange for this measure to be carried out on the affected vehicles immediately.

Model type	718 (982)
Model year	2021
Number	3

Parts required (only if necessary)

Part No.	Designation	Quantity/vehicle	Parts return
99907357701	Oval-head screw	2 ea. (only if required)	No

Parts Ordering Parts can be ordered immediately, as needed

Warranty processing

Validity:

This workshop campaign will be carried out up to 12/17/2025 and will be closed by the specified date. Please note that warranty claims can only be processed before this date.

Scope 2: Reworking screws on front side member

- **Only for USA vehicles (C02)**

Damage code	WLN5 66 000
Repair code	1
Working time	52 TU

Please enter the campaign that was carried out in the Warranty and Maintenance booklet for the vehicle.

Further information

Work instruction	TI No. 214/20, Group 5, Service, WLN5
Vehicle list and allocation	See PCSS or attached list for reference
Technical Information	See PCSS or Aftersales Document Database

[WLN5 VIN List.xlsx](#)

8.1 KB

(71 views)

Created by [Ryan Cooney](#) on Jan 15, 2021 10:09 PM. Last modified by [Ryan Cooney](#) on Jan 15, 2021 10:19 PM.

589 Views [Report Abuse](#)

Categories: Cayman, Workshop Campaigns, Boxster

Tags : [workshop campaign](#), [my l](#), [718 \(982\)](#), [wln5](#)

Content and Topics

Personal

Manage

Create

Your Groups >

Edit Profile >

Admin Console >

Discussion >

Your Content >

Change Password >

PPN Administration >

Files >

Your Places >

Document >

Collaboration >

Document

Blog Post >

Poll >

Event >

Photo Album >

Idea >

Space >

Group >

© 2021 Dr. Ing. h.c. F. Porsche AG. Legal notice. Copyright. Terms of use. Privacy Policy. Cookie Policy. 009