

TECHNICAL TOPICS

BODY/CHASSIS



Front Power Seat Switch Malfunction	20MY Range Rover
<p>Customer Voice:</p> <ul style="list-style-type: none"> A customer may report that the front seat is not operating properly from the switch pack, features like seat massage, lumbar support, seat memory, etc. is not working from the switch. <p>Technical Description:</p> <ul style="list-style-type: none"> The front seat switch pack is being replaced for different operational concerns. <p>Status:</p> <ul style="list-style-type: none"> Engineering is investigating reports of front seat switch pack failures. To support this investigation, should a customer report a concern regarding seat switch operation and the cause is determined to be due to a faulty seat switch pack, please submit an EPQR with details of the seat operational concern. 	<p>The diagram shows a top-down view of the front seats in a vehicle. Ten numbered callouts (1-10) point to various switch packs and components on the seats, including the driver's seat (left) and passenger's seat (right). Callout 10 points to a central control panel between the seats. The diagram is labeled 'E212963' in the bottom left corner.</p>

