

27-21-01TT – Distance Regulation Control Module -*J428*-, VAS 6430 Calibration Mirrors

Release date:

Transaction No:

02/19/2021

Condition

ATTENTION:

THIS IS A TECH TIP, NOT A TECHNICAL BULLETIN.

TECH TIPS ARE NOT ASSOCIATED WITH WARRANTY CLAIMING.

| Applicable Vehicle | s | | | | | | | |
|--------------------|-----------|-----------|-------------|----------------|--------------|--|--|--|
| Model(s) | Year | Eng. Code | Trans. Code | VIN Range From | VIN Range To | | | |
| All | 2016-2021 | All | All | All | All | | | |

| Revision Table | | | | | | | | |
|-----------------|----------------|----------------|-----------------------|--|--|--|--|--|
| Instance Number | Published Date | Version Number | Reason For Update | | | | | |
| 2062414/1 | 2/19/21 | 27-21-01 | Original publication. | | | | | |

Technical Background

Information regarding the calibration mirrors available for the special tool VAS 6430 calibration boards.

Service

When performing a calibration of the Distance Regulation Control Module -*J428*-, be sure to reference the instructions in ELSA for not only the positioning of the VAS 6430 calibration boards, but also which mirror should be used.

There are currently two mirrors available when performing the calibration, the VAS 6430/3 and the VAS 6430/10. These mirrors are able to be differentiated from each other by looking for the presence of the "1, 2, 3" adjustment knob. Only the VAS 6430/3 will have this adjustment knob.

Also, the VAS 6430/10 is slightly larger than the VAS 6430/3. Refer to the photos below for an example of the mirrors. If the incorrect mirror is used, the calibration may complete successfully, but after driving for a period of time, a fault for "sensor misadjusted" may return. If this occurs, double check ELSA and ensure that the proper calibration mirror was used.



27-21-01TT – Distance Regulation Control Module -*J428*-, VAS 6430 Calibration Mirrors

Release date:

Transaction No:

02/19/2021



Notice the adjustment knob on the upper left corner of the mirror

Figure 1: VAS 6430/3



Notice the lack of an adjustment knob where the VAS 6430/3 has one

Figure 2: VAS 6430/10

Additional Information

© 2021 Volkswagen Group of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.