

ABS 11 SPN 807



[Adam Mechanic](#) 3 posts since Feb 7, 2020

ABS 11 SPN 807 Feb 5, 2021 3:10 PM

14 Cascadia FJ1682, has ABS11 SPN807 on dash, anything i can find online says it has to do with the Dif 2 ASR Valve. Ive checked this valve out, have even replaced it, (those O-rings are a pain btw to keep in place) and have sprayed a water/soap solution around it to make sure there is no air leaking from it. The wheel speed sensors voltages and resistances check out within normal spec. We had it into Freightliner once before and they said it was a fuse, ive checked every possible fuse on this thing and relay and nothing it blown or damaged and i cant get them to tell me exactly which "fuse" was bad. Where do i go from here?