

**From:** Sleeper, Tony (590) <tony.sleeper@daimler.com>

**Sent:** Friday, February 26, 2021 6:43 AM

**To:** espejelj@tci-leasing.com

**Subject:** Unit KU1804 Fuel Pump

Good Morning Joel,

---

I am a service engineer for Detroit Diesel. We recently learned of an issue with a small number of Detroit medium duty fuel pumps. The supplier has found a machining burr inside the pump that could result in failure of the pump as well as the entire engine. One of these units is owned by TCI Leasing. I would like to get it scheduled into a local dealer to have the fuel pump replaced under warranty.

Vehicle VIN is KU1804

If you have a preferred dealer, I can help get the truck scheduled in. Please let me know.

Thank you,

Tony Sleeper  
Failure Analysis Engineer – Fuel & Air System  
Powertrain Service Engineering  
Daimler Trucks North America

Phone: +1 (313) 592-5087

Mobile: +1 (313) 354-3774

