

**On-car analysis list from March 2nd, 2021**  
**please contact VW Helpline before attempting repair**

	Models	MY	Engine	Transmission	Topic	Customer Complaint
<b>Powertrain</b>	Atlas, Atlas Cross Sport	20-21	3.6L (CDVC)	All	MIL-on P0087 P0148 P053F	Customer states MIL-on <b>(Must have P0087, P0148 and/or P053F fault codes)</b> <b>(Untouched vehicles)</b>
<b>Electrical</b>	Passat	20	All	All	Radio Freeze/Reboot	Customer states radio is freezing, rebooting, or blank display. <b>(Untouched vehicles)</b>
	Atlas, Atlas Cross Sport	19-21	All	All	MFI DTC U019900	Customer states "driver door contact switch error" and/or "electronic parking brake fault" in the MFI <b>(Must have DTC U019900 in the ECM)</b> <b>(Untouched vehicles)</b>
<b>Other</b>	Golf, Golf SportWagen, Jetta GLI	17-19	All	All	Suction Jet Pump	Customer states fuel odor/leak in the rear part of the vehicle <b>(without</b> a punctured fuel tank, hoses or pipes) or difficulty fueling fuel tank or fuel coming back up filler neck <b>(untouched vehicles)</b>