



# Technical Service Bulletin

## 90 DTC U110100 is stored in the driver assistance systems control module

90 21 95 2062601/1 March 8, 2021.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A6, A7, A8, S8, Q8, and Audi e-tron quattro	2019 - 2021	All	Driver assistance systems control module
A6 allroad, S6, S7, RS 7, Q7, SQ7, SQ8, and Audi e-tron Sportback	2020 - 2021	All	Driver assistance systems control module
A6 Avant, RS 6 Avant	2021	All	Driver assistance systems control module

## Condition

### Customer states:

- No customer concerns, it is found during PDI or any other diagnostic work.

### Workshop findings:

The following DTC may be stored statically in the driver assistance systems control module, J1121 (address word 00A5):

- **DTC U110100** (Component protection active) with symptom code 15361024.



### Note:

This TSB is only applicable to vehicles which had their driver assistance systems control module, J1121 (address word 00A5) updated to SW 0365.

Please follow the ODIS test plan for vehicles that were delivered with SW 0365 or newer from the factory.

## Technical Background

Diagnosis issue in the driver assistance systems control module, J1121 (address word 00A5).

## Production Solution

Not applicable.



# Technical Service Bulletin

---

## Service

DTC U110100 is stored erroneously in the driver assistance systems control module, J1121 (address word 00A5) (Ghost DTC).

1. Do not perform any repairs. Any repairs or part replacements for this concern may be denied.
2. This condition is normal.



### Note:

This DTC neither causes any problems with the functionality of the vehicle nor any warning messages visible to the customer.

## Warranty

This TSB is informational only and not applicable to any Audi Warranty.

## Additional Information

All part and service references provided in this TSB (2062601) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2021 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.